

DMKSY-SC

FIELD INSPECTION REPORT

Date of Inspection : 31/12/2020		District: Samardpur
Division : Samardpur		Length (km): 1.17 km
Name of the Road: Argun Thakur ka ghos <del>to</del> (wastage) to		
Scheme/Programme: MAINTENANCE		Barraiparpur Pawan Tala Tal
Package No.:		
Status of the Project: <input checked="" type="checkbox"/> Ongoing / <input type="checkbox"/> Completed / Under Maintenance		Road Id No.:
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U
c)	Condition of railings/slab/approach for Bridges	S/SR/U
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4. Compliance History		
a)	Status of ATR's & any others	— No —

Overall Rating :

Satisfactory (S)	NA
Satisfactory but requires Improvement (SRI)	.
Unsatisfactory (U)	

C&B work is in Progress (work not completed)

*[Signature]*  
31/12/2020  
(Signature)

NAME: PISUJ RAY