

15:57
a R. Gumti Lo26 to Samardah Ch 2.4800
08
1868

FIELD INSPECTION REPORT

old PMGSY

Date of Inspection:	04/01/2021	District:	Bhojpur
Location:	Jagdishpur	Length (km):	1.487 km
Name of the Road:	LO 42 Katelya R Gumti Lo26 to Samardah Ch 2.4800		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR07R-225	Road Id No.:	10401202092
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

04/01/2021
J2

(Signature) 04/01/2020
AE