

FIELD INSPECTION REPORT

old MMSY (Gen)

Date of Inspection :	04/01/2021	District:	Bhojpur
Location :	RW 3 Jughurapur	Length (km):	0.900 Km
Name of the Road:	NH 84 Bihya chaurasta to Nawadich		
Name/Programme:	MAINTENANCE		
Page No.:		Road Id No.:	10401712026
State of the Project:	Ongoing/Completed/Under Maintenance		
Is a case of:	New Connectivity/Up gradation/ Maintenance		

Parameters to be checked	Remarks
Pavement	
Road Junction condition	S/U S
Condition of Surfacing	S/U S
Riding Quality	S/U S
Road Camber	S/U S
Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
Contraction Joints provided or not (CC Pavement)	Yes/No
Compaction of flank/slope & raincuts if any	Yes/No N/O
Cross Drainage	
Condition of head walls in Hume pipe culverts including its painting	S/SRI/U SRI
Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U SRI
Condition of railings/slab/approach for Bridges	S/SRI/U SRI
Road Furniture	
Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No N/O
Compliance History	
Status of ATR's & any others	

Overall Rating :	Satisfactory (S)
	Satisfactory but requires Improvement (SRI)
	Unsatisfactory (U)

04/01/2021
JE

04/01/2020
(Signature) AS