## FIELD INSPECTION REPORT

	1201	Status of ATR's & any others	a)
		Compliance History	4.
3	Yes/No	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	a)
		Road Furniture	3.
	S/SRI/U	Condition of railings/slab/approach for Bridges	c)
3	S/SRI/U	Condition of Abutment & Wing walls, Slab in RCC culverts	ь)
	S/SRI/U	Condition of head walls in Hume pipe culverts including its painting	a)
		Cross Drainage	2.
	Yes/No	Compaction of flank/slope & raincuts if any	g)
	Yes/No	Contraction Joints provided or not (CC Pavement)	ŋ
3	Yes/No	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	e)
	S/U	Road Camber	d)
	S/U	Riding Quality	c)
	S/U	Condition of Surfacing	b)
	S/U	Road Junction condition	a)
		Pavement	
	Remarks	Parameters to be checked	SI. No.
		case of: New Connectivity/Up gradation/ Maintenance	Work is a case of:
		Status of the Project: Ongoing/Completed/Under Maintenance	Status of t
		o.: Road Id No.:	Package No.:
		Scheme/Programme: MAINTENANCE	Scheme/Pr
		a Baha Bhola c	Name of the
•		Division: Samontyluz Length (km): 2.070km	Division:
		The ni specion: 31/15/500 nistrict: Samonphy	Date of III

Overall Rating

Satisfactory but requires Improvement (SRI) Satisfactory (S) Unsatisfactory (U)

Earthwale is in (roquens (work not completed)

(Signature)