## FIELD INSPECTION REPORT

Date of	Inspection:	4/1/21	District: Patua	
Division: Masaurhi			Length (km): 0.975K	
Name (	of the Road: K	istipu Mac	dhabar Sc Kantahi el	nak tak P
Schem	e/Programme:	MAINTENANC	E HABARD   Mainten	
Packag		To	Road Id No.:	
		Committee of the Commit	eted/Under Maintenance	
Work	s a case of:		ty/Up gradation/ Maintenance	
SI. No.		Parameter:	s to be checked	Remarks
1.	Pavement			
a)	Road Junction condition			S S/U
b)	Condition of Surfacing			U S/U
c)	Riding Quality			s s/U
d)	Road Camber			s s/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			No Yes/No
()	Contraction Joints provided or not (CC Pavement)			75 Yes/No
g) .	Compaction of flank/slope & raincuts if any			MoYes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			APT CS/NO
4,	Compliance H	istory		THE STREET
a)	Status of ATR'	s & any others		HOATR

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	W

NAME: ASSH. Engineer

(Signature)