

FIELD INSPECTION REPORT

Date of Inspection :	31/12/2020	District :	Pune
Division :	Maharashtra	Name of the Road :	Pradhikarn Marg, Pune
Scheme/Programme :	MAINTENANCE	Length (km) :	0.60 km
Package No. :		Work is a case of :	Ongoing/Completed/Under Maintenance
Status of the Project :		Road ID No. :	1515/1411
Work is a case of :	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing	U S/U	
c)	Riding Quality	U S/U	
d)	Road Camber	U S/U	
e)	Whether free from defects such as aggregates in case of CC Pavement.	U S/U	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	Yes/No	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRU	
c)	Condition of railings/slab/approach for Bridges	S/SRU	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S/SRU	
4.	Compliance History		
a)	Status of ATR's & any others	Yes/No	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRU)	
Unsatisfactory (U)	U

NAME: Poornima Prakash
Asstt. Engineer

31/12/20
 (Signature)