

FIELD INSPECTION REPORT

Date of Inspection : 4/1/21		District: Patna	
Division : Masaurhi		Length (km): 2.372 Km	
Name of the Road: Kosnt Madhuban Path to Satpara Path			
Scheme/Programme:		MAINTENANCE MMGSY (SC) / Maintenance	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	U S/U	
b)	Condition of Surfacing	U S/U	
c)	Riding Quality	U S/U	
d)	Road Camber	U S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes Yes/No	
g)	Compaction of flank/slope & raincuts if any	No Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	No Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	U

Note: The road is damaged since in some stretch part of carriage way & Roadway falls under PVT law. This part has been cut by the order of Honorable Kijica

4/1/21
(Signature)

NAME: Pushkar Prasad
S. H. Singh