

FIELD INSPECTION REPORT

Date of Inspection : 31-12-2020 District: PURNIA
 Division : DHAMDANA Length (km): 4.259 km
 Name of the Road: Kabiya Bazar Ball Asharti Kabiya Mandal Tola
 Scheme/Programme: MAINTENANCE
 Package No.: MML 59 Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a.	Road Junction condition	S/
b.	Condition of Surfacing	A/C
c.	Binding Quality	S/
d.	Road Camber	1/
e.	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f.	Contraction Joints provided or not (CC Pavement)	Yes/No
g.	Compaction of flank/slope & raincuts if any	Yes/No
2.	Gross Drainage	
a.	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b.	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c.	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a.	Whether sign boards/informatory/cautionary Board/km & 200m stores/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a.	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

U.

Pranav
 31-12-2020
 (Signature)

NAME: PRANAV KUMAR
 (S.E.)