FIELD INSPECTION REPORT

| Date of Inspection: 03 01 2021 | | | District: Katihar | | |
|--|--|---|---------------------------------|--|--|
| | | | Length (Km): 2.151 Km | | |
| 23.13.1 | f the Road: | 052 - Devipur vi | llage to Kamla | Kanhi MMSNY | |
| | Br | 052 - Devipu vi idge (Track-46) | | | |
| Scheme/ | Programme: | Maintenance | | | |
| Package | No.: 8 | R-16-R-242 | Road ID No.: | | |
| Status of the Project : | | Ongoing/Completed/Under Ma | r Maintenance Under Maintenance | | |
| Work is a case of: New Connectivity/Up gradation/Maintenance | | | | | |
| Sl. No. | STATE OF THE STATE | Parameters to be Che | PARTIES . | Remarks | |
| 1). | Pavement | Control of | Allen V | the state of the s | |
| a) | Road Junction co | ndition | | ✓Ś/U | |
| b) | Condition of Surfacing | | | S/U | |
| c) | Riding Quality | | | ✓S/U | |
| d) | Road Camber | | | ✓S/U | |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | | e of Yes/No | |
| f) | Contraction Joints provided or not (CC Pavement) | | | ✓Yes/No | |
| g) | Compaction of Flank/Slope & Raincuts if any | | | ✓Yes/No | |
| 2). | Gross Drainage | | | | |
| a) | Condition of Head walls in Hume Pipe Culverts including its painting | | | ✓S/SRI/U | |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts. | | | ✓\$/\$RI/U | |
| | Condition of Railings/Slab/Approach for Bridges | | | ✓S/SRI/U | |
| | Pood Rurniture | | | A STATE OF THE STA | |
| a) | Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained | | | Yes/No | |
| 4). | Compliance Hist | ory | | | |
| a) | Status of ATR's & | any others | | | |
| Overell B | Dating : | Satisfactory (S) | | | |

| Satisfactory (S) | |
|---|-----|
| Satisfactory but requires Improvement (SRI) | SRI |
| Unsatisfactory (U) | |

Name: Dharmendor Kumal
Degisnation: JE (Kursedg.)
RWD, Works Division, Katihar.

Scanned by CamScanner

(Signature)