FIELD INSPECTION REPORT

		THE HARDE		
Date of I	nspection: [8-12-20	District: Malanda	
Division: Bilharsarit			Length (km): 6.823 Km	
Name of	the Road: Lo	023-NH82 to R	aghopus	
Scheme/Programme: MAINTENANCE		MAINTENANCE	PMGSY	
Package No.:			Road Id No.:	
Status of the Project:		Ongoing/Completed/Under, Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
Sl. No.		Parameters to	be checked	Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d) 8	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed nggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage			
(a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
()	Condition of railings/slab/approach for Bridges			S/SRI/U

Overall Rating :

Road Furniture

Compliance History

Status of ATR's & any others

c)

3.

a)

4.

a)

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Yes/No

Wil

yes

(Signature)

NAME: Ram Akbal pd. Singh yadal

Condition of railings/slab/approach for Bridges

Whether sign boards/informatory/cautionary Board/km & 200m

stones/Pavement road markings are provided and maintained

DESIGNATION: Assistant Engineer

Scanned with CamScanner