FIELD INSPECTION REPORT

_		TIBDO HISTER		· service and serv
Date of	f Inspection:	23 12 20	District: Arana	
Divisio	n: forbesg	Ort	Length (km): 1.672	
Name of the Road: middle school Kavaya to Bousi Chouk.				
Schem	c/Programme:	MAINTENANCE		
Packag		and materials were embroomed the children delegation of the employment of the children and the children is delegated to the children and the c	Rond Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance Remarks		
Sl. No.		Parameters to	wellockou	1cemarks
1	Pavement	and the second of the		
a)	Road Junction	A. Marchael A. Marchael and A.		√S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			√8/U
	Road Camber			√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			s/srî/u
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			√8/SRI/U
c)	Condition of railings/słab/approach for Bridges			8/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance His	tory	1000年,在阿尔斯斯	
a)	Status of ATR's	& any others		40

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	,

NAME: Bridest worn ground fam AE) Rangerg