## FIELD INSPECTION REPORT

			or reprotes	
Date of	Inspection:	strict: Myzulfaspys		
Division: MZaffgebys East-01 Len			ength (km): 1.320 KM	
.vame (	n the Road: 7	Wasikabur ( m.	yourity Hall to t	www.kab.
	Programme:	MAINTENANCE	Bhumhas 1	That Tol
Packag			4010.10.1 31507212	2032
	of the Project:	Ongoing/Completed/Und	ier Mainténance	
	s a case of:	New Connectivity/Up gr	adation/ Maintenance	
Sl. No.	Parameters to be checked			Remarks
1.	Pavement	A second second	Mile Later Co.	
a)	Road Junction condition			·S/U
b)	Condition of Surfacing			S/U•
c)	Riding Quality			S/U
d)	Road Camber			~8/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No.
f)	Contraction Joints provided or not (CC Pavement)			Yes No
g)	Compaction of flank/slope & raincuts if any			Yes No
2.	Cross Drainag	e		100
a)	Condition of he	on of head walls in Hume pipe culverts including its painting		S/SRI/U
p)	Condition of Abutment & Wing walls, Slab in RCC culverts		⊀/SRI/U	
c)	Condition of railings/slab/approach for Bridges		⊀SRI/U	
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No.	
4.	Compliance His	story	AN CALL	
a)	Status of ATR's	& any others		

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

30.12.2020 SE

Stel ... No Signature)

NAME:

DESIGNATION: