

FIELD INSPECTION REPORT

Date of Inspection : 04.1.2021		District: Silchar	
Division : Silchar		Length (km): 1.68 km.	
Name of the Road: PWD Road to Tale Dangaicha.			
Scheme/Programme: MAINTENANCE		Road Id No.:	
Package No.: BR-33R-405		Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1. Pavement			
a)	Road Junction condition		✓S/U
b)	Condition of Surfacing		✓S/U
c)	Riding Quality		✓S/U
d)	Road Camber		✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)		✓Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2. Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting		✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges		✓S/SRI/U
3. Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		✓Yes/No
4. Compliance History			
a)	Status of ATR's & any others		NO.

Overall Rating :

Satisfactory (S)	\$
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: *Mujibur Rahman*

DESIGNATION: J.B.

[Signature]
04/1/21
(Signature)
J.B.