

FIELD INSPECTION REPORT

Date of Inspection : 04-01-2021 District : MAHARASHTRA
 Division : MAHARASHTRA Length (km) :
 Name of the Road : SH Baba Gopal D/yalda to D/yalda gorry
 Scheme/Programme : MAINTENANCE
 Package No. : Road Id No. :
 Status of the Project : Ongoing/Completed/Under Maintenance
 Work is a case of : New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/L
b)	Condition of Surfacing	✓ S/L
c)	Riding Quality	✓ S/L
d)	Road Camber	✓ S/L
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRLU
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRLU
c)	Condition of railings/slab/approach for Bridges	S/SRLU
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO.

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	S.R.I
Unsatisfactory (U)	

(Signature) 4/01/21

NAME : Ajay Kumar Sharma

DESIGNATION : Junior Engineer