FIELD INSPECTION REPORT

Date of Inspection: 0	3.01.9021	District: Gaya	
Division: RwD (w) Div. Tekari		Length (km): 2.467	
	06 to Nimi	2.45/	
Scheme/Programme:		PMGSY	
Package No.: BR-12R	2 - 872	Road Id No.:	
Status of the Project:	Ongoing/Completed	/Under Maintenance	
Work is a case of:	New Conhectivity/Up gradation/ Maintenance		
Package No.: BR-12K Status of the Project:	- &73 Ongoing/Completed	Road Id No.: /Under Maintenance	

Sl. No.	Parameters to be checked	Remarks
1,	Pavement	
a)	Road Junction condition	S/U s
b)	Condition of Surfacing	S/U s
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Ye
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	s/sri/u 5
c)	Condition of railings/slab/approach for Bridges	S/SRI/U S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No γe
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (\$RI)
Unsatisfactory (U)	

(Signature)
AE, RWD (W) Div. Telcari

NAME: Armash Kunas