

# FIELD INSPECTION REPORT


Date of Inspection : 01.01.2021	District: Gaya
Division : RWD(W) Div. Tekari	Length (km): 2.369 km
Name of the Road: Tikari Bela road to Badhu Bigha	
Scheme/Programme: MAINTENANCE	PMGSY
Package No.: BR-12R-828	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		S/U S
b)	Condition of Surfacing		S/U S
c)	Riding Quality		S/U S
d)	Road Camber		S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No Yes
f)	Contraction Joints provided or not (CC Pavement)		Yes/No Yes
g)	Compaction of flank/slope & raincuts if any		Yes/No Yes
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U S
c)	Condition of railings/slab/approach for Bridges		S/SRI/U S
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m	Yes/No Yes
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Avinash Kumar

  
 (Signature)  
 A.E. RWD(W) Div. Tekari