

FIELD INSPECTION REPORT

Date of Inspection: 31-12-2020		District: GAYA	
Division: Nirmal-Bathani		Length (Km.): 0.545 KM	
Scheme/Programme:		MAINTENANCE	
Package No.: Khatiyabad to Jagdaha		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameters to be checked		Remarks
1	Pavement	S	S/U
a)	Road Junction condition	S	S/U
b)	Condition of Surfacing	S	S/U
c)	Riding Quality	S	S/U
d)	Road Gamber	Yes	Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes	Yes/No
g)	Compaction of flank/slope & raincuts if any		
2	Cross Drainage	S	S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting	NA	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA	S/SRI/U
c)	Condition of railings/slab/approach for Bridges		
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes	Yes/No
4	Compliance History		ATR
a)	Status of ATR's & any others.		

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

checked
31-12-2020
J.E