

FIELD INSPECTION REPORT

Date of Inspection: 30.12.2020	District: GAYA	
Division: Neemchak Bathani	Length (Km): 5.90 km	
Scheme/Programme: Narmada	Road Name: Chakra Horizontal to Jethiyani Chakra Rd	
Project No.: G.T.S.N.Y.	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NO Yes/No
f)	Contraction Joints provided or not (CC Pavement)	YES Yes/No
g)	Compaction of flank/slope & cutouts if any	YES Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	SRI S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA S/SRI/U
c)	Condition of railings/slab approach for Bridges	NA S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	YES Yes/No
4	Compliance History	
a)	Status of ATR's & any others.	NO ATR

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires improvement (SRI)	SRI
Unsatisfactory (U)	—

Day 2012 2020
J E