

FIELD INSPECTION REPORT

Date of Inspection :		District : GAYA	
Division : Neechhak Bathani		Length (Km.) : 0.750 km	
Scheme/Programme :		Name of the Project : MAINTENANCE Karamnark to Gaya Nawada Road to bore road	
Package No. : GTSNY		Road Id No. :	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	S	S/U
b)	Condition of Surfacing	U	S/U
c)	Riding Quality	U	S/U
d)	Road Camber	S	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NO	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	yes	Yes/No
g)	Compaction of flank/slope & cutouts if any	yes	Yes/No
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	SRI	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA	S/SRI/U
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	NO	Yes/No
4	Compliance History		
a)	Status of ATR's & any others.	No ATR	+

Overall Rating :

Satisfactory (S)	
Satisfactory but requires improvement (SRI)	SRI
Unsatisfactory (U)	

Devy
30.12.2020