

FIELD INSPECTION REPORT

Date of Inspection : 30.12.2020		District : GAYA	
Division : Meemchak Bathani		Length (Km. : 1.25 km	
Scheme/Programme:		MAINTENANCE Shajadpur Rd to G401 Passh 9 Meemchak - Yaddav Jola.	
Package No. : GT.S.N.Y		Road Id No. :	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameters to be checked		Remarks
1 Pavement			
a)	Road Junction condition	S	S/U
b)	Condition of Surfacing	S	S/U
c)	Riding Quality	S	S/U
d)	Road Camber	S	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes	Yes/No
g)	Compaction of flank/slope & raincuts if any	NO	Yes/No
2. Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	SRI	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA	S/SRI/U
3 Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	NO	Yes/No
4 Compliance History			
a)	Status of ATR's & any others.	NO ATR	-

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires improvement (SRI)	• SRI
Unsatisfactory (U)	—

30.12.2020
S.E