FIELD INSPECTION REPORT

Date of Inspection : District : Bhagalpur			
Division: Bhagalpur Length (Km): 1-728 km.			
Name of the Road: Amarpus Navtolia to Viaurachhatci ka shocke Bhog Dradhi Tak			
	/ Programme :		
Package No.: 20703213026			
Status of the Project: Ongoing / Completed / Under Maintenance			
Vork is	a case of : New Connectivity / Up gradation / Maintenance	:e	
SL. No.	Parameters to be checked	Remarks	
1.	Pavement	,	
a)	Road Junction condition	VS/U	
b)	Condition of Surfacing	_R/U	
c)	Riding Quality	SIU	
d)	Road Camber	-81U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	^
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Nes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/JU	,
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U	(
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	> N.A.
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	~Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	N.A	
erall Ra	iting:	1	
	Satisfactory (S)		
	Satisfactory but requires Improvement (SRI)	9.0	· ·
	Unsatisfactory (U)	8.R.I.	
lote :			

NAME:

DESIGNATION:

Mally Signature 9 122020