FIELD INSPECTION REPORT

Date of Inspection: 03 01 2021 District: Katihar					
Division : Katihar			Length (Km): 1,550 KM		
Name of	the Road: LU 8	7 to panipur			
Scheme/Programme: Maintenance		Maintenance	•	×	
Package No.:			Road ID No. :		
Status of the Project:		Ongoing/Completed/Under Maintenance			
Work is a case of: New O		New Connectivity/Up grad	w Connectivity/Up gradation/Maintenance		
Sl. No	Parameters to be Checked		Remarks		
1).	Pavement				
a)	Road Junction condition			√ 8/U	
b)	Condition of Surfacing			∽ S/U	
c)	Riding Quality			~8 7U	
d)	Road Camber			~\$ 7U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			¥es/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of Flank/Slope & Raincuts if any			Yes/No	
2).	Cross Drainage				
a)	Condition of Head walls in Hume Pipe Culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.			S/SRI/U NA	
c)	Condition of Railings/Slab/Approach for Bridges			S/SRI/U N, A	
3).	Road Furniture				
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained			Yes/No	
4).	Compliance History			No	
a)	Status of ATR's & any others				
V		Satisfactory (S)		- K. 13 1	
Overall Rating :			es Improvement (SRI)	SRI	

Unsatisfactory (U)

(Signature)

Name: Dilip kumar

Degisnation: 7.E

RWD, Works Division, Katihar.