FIELD INSPECTION REPORT

		1.		
Date of Inspection: 28.12.20			District: East champaran	
Division: Rayand			Langely (land), dans	
Name	of the Road: 6	42-6013 to Jag	dhardhab	
Scheme/Programme: MAINTENANCE PMGSY				a towns displaced to the production and the day beautiful.
		11R-643		50 2067
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
Sl. No.		Parameters to be checked		Remarks
1.	Pavement			
a)	Road Junction condition			
b)	Condition of Surfacing			
c)	Riding Quality			\S/U
d)	Road Camber	Road Camber		
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
Ŋ	Contraction Joints provided or not (CC Pavement) Yes/No			Yes/No
g)		Compaction of flank/slope & raincuts if any		
2.	Cross Drainage Yes/No			
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			
c)	Condition of railings/slab/server 1 C. D. 1			NS/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History	ory		
a)	Status of ATR's &	N.A.		

Overall Rating

Satisfactory (S)	151
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Møthilest kumer ligh DESIGNATION: Jynter Ergisser, Lexaul