

# FIELD INSPECTION REPORT

Date of Inspection : 23/12/20	District: East Champaran
Division : Roxaul	Length (km): 1.319
Name of the Road: Lo38-To4 to Bauman's Tola	
Scheme/Programme: MAINTENANCE	PMGSY
Package No.: BR-11R-683	Road Id No.: 31708502082
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A.
c)	Condition of railings/slab/approach for Bridges	N.A.
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	N.A.

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

23/12/20  
(Signature)

NAME: Methilal Kumar Singh

DESIGNATION: Junior Engineer, Roxaul