

FIELD INSPECTION REPORT

| | | |
|--|--|----------------------------------|
| Date of Inspection : 28.12.20 | | District: East Champaran |
| Division : <u>Raxaul</u> | | Length (km): 1.125 |
| Name of the Road: <u>Losb - Losb Leekhamanwa to Pokhara Tola</u> | | |
| Scheme/Programme: MAINTENANCE | | <u>PH95Y</u> |
| Package No.: <u>682</u> | | Road Id No.: <u>3170850 2084</u> |
| Status of the Project: Ongoing/Completed/Under Maintenance | | |
| Work is a case of: New Connectivity/Up gradation/ Maintenance | | |

| Sl.No. | Parameters to be checked | Remarks |
|--------|--|----------|
| 1. | Pavement | |
| a) | Road Junction condition | ✓ S/U |
| b) | Condition of Surfacing | ✓ S/U |
| c) | Riding Quality | ✓ S/U |
| d) | Road Camber | ✓ S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | ✓ Yes/No |
| f) | Contraction Joints provided or not (CC Pavement) | ✓ Yes/No |
| g) | Compaction of flank/slope & raincuts if any | ✓ Yes/No |
| 2. | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SRI/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | S/SRI/U |
| c) | Condition of railings/slab/approach for Bridges | S/SRI/U |
| 3. | Road Furniture | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓ Yes/No |
| 4. | Compliance History | |
| a) | Status of ATR's & any others | N.A. |

Overall Rating :

| | |
|---|-----|
| Satisfactory (S) | 'S' |
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

Chhish
28.12.20
(Signature)

NAME: Mr. Hitesh Kumar Singh

DESIGNATION: Junior Engineer, Raxaul