

FIELD INSPECTION REPORT

Date of Inspection : 04/01/2021	District: MADHUBANI
Division : MADHUBANI	Length (km): 0.750 km
Name of the Road: SH paswan to MANDAL tol pass	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/ <u>Under Maintenance</u>
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SU
b)	Condition of Surfacing	SU <i>Some potholes</i>
c)	Riding Quality	SU ✓
d)	Road Camber	SU.
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No <i>N/A</i>
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NO.

Overall Rating

Satisfactory (S)	<i>Unsatisfactory</i>
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

04/01/21
(Signature)