

FIELD INSPECTION REPORT

Date of Inspection: 10/12/2020 District: Patna
 Location: Paliganj Length (km): 1.235
 Name of the Road: Madaripur to Baghmohapur
 Scheme Programme: MAINTENANCE
 Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance:
 This is a case of: New Connectivity/Up gradation/ Maintenance ☒

No.	Parameters to be checked	Remarks
Pavement		
	Road Junction condition	✓ S/U
	Condition of Surfacing	✓ S/U
	Riding Quality	✓ U
	Road Camber	✓ S/U
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
	Compaction of flank slope & raincuts if any	✓ Yes/No
Cross Drainage		
	Condition of head walls & frame pipe culverts including its painting	S/SRI/U
	Condition of Abutment & Wing walls. Slab in RCC culverts	S/SRI/U
	Condition of railings slope approach for Bridges	S/SRI/U
Road Furniture		
	Whether sign boards/informatory cautionary Board/km & 200m stones Pavement road markings are provided and maintained	✓ Yes/No
Compliance History		
	Status of ATR's & any others	

Overall Rating :

Satisfactory (S) 'S'
 Satisfactory but requires Improvement (SRI)
 Unsatisfactory (U)

(Signature)

10/12/2020
 Jcl