## FIELD INSPECTION REPORT

Date	of Inspection and an arms of the section of the sec	
Divis	Date of Inspection: 01-01-2021 District: SUPAUL  Division: SUPAUL Length (low) Control (low)	
Name of the Road: James and Length (km): 2.765		
Schen	ne/Programmer MAINTEN LO Maryan Tola	
	MMC25 V(SCI	
	Doe J T I N	901330
Status of the Project: Ongoing/Completed/Under Maintenance  Work is a case of: New Connectivity/Up gradation/ Maintenance  Sl. No.		401000
Sl. No	Parameters to be checked	
1.	Pavement	Remarks
a)	Road Junction condition	
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	<b>√</b> \$/U
e)	Whether free from defects such as visible cracks, expose aggregates in case of CC Pavement.	√S/U ed
f)	Contraction Joints provided or not (CC Pavement)	Yes/No-NA-
g)	Compaction of flank/slope & raincuts if any	Yes/Non A
2.	Cross Drainage	Yes/No
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	· <del>S/SRI/U</del> N.A·
3.	Road Furniture	S/SRI/UA.
a) .	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4. (	Compliance History	- 20,140
a) S	Status of ATR's & any others	
erall Da	4	No Any ATR

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	
	U

01.01.2021 (Signature)

NAME: Ran Vijay Kumar DESIGNATION: A.E. R.W.D., Sufaul

Scanned by CamScanner