PMGSY FIELD INSPECTION REPORT

Date of Inspection :	13-01-21	District: Roktos	
me et a la l		Length (km): 20 "50	
Name of the Road:	02 - Karaga	har Barban readto Dharmoura re	
Scheme/Programme:	MAINTENANC	E	
Package No.: BR-28R-560		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

SI. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber		
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		
g)	Compaction of flank/slope & raincuts if any	/Yes/No	
2, ,	Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	/S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.1	Compliance Flatory		
a)	Status of ATR's & any others	40	

Overall Rating

Satisfactory (S)	1,8,
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Massage of .

(Signature)

NAME: Makesh Poosed Sal

DESIGNATION: 3 臣