

FIELD INSPECTION REPORT

MMGSY (SC)

Date of Inspection : 12-12-2020	District: Samastipur
Division : Samastipur	Length (km): 0.85 km
Name of the Road: LOST to Mukund pur. Paschim	
Scheme/Programme: MAINTENANCE	
Package No.:	
Status of the Project: Ongoing/Completed/Under Maintenance	Road Id No.: 32010101397
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S/U
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others - <i>Previous ATR not Regreted due to grading work.</i>	NA

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—SRI—
Unsatisfactory (U)	—U—

Not Applied

Yes

Yes

Yes

↑

NA

↓

No.

NA

SRI

Santosh
14-12-2020

NAME: SANTOSH KR. THAKUR
JE R.W.D. Samastipur - 2

(Signature)

AE

AE
12/12/20