## FIELD INSPECTION REPORT

Date of Ir	spection: 2	2.12.2020	District: SUPAUL		
Division: KISHAMPUL			Length (km): 1.10 Km		
Name of	the Road: P	w) road A	o yadar tola		
Scheme/I					
				4901817	
Status of the Project: Ongoing/Completed/				***************************************	
Work is a case of: New Connectivity/Up gradation/ Maintenance				17. 1 2 2 2 3 1 1 1 1 1 1	
Sl. No.		Parameters to	be checked	Remarks	
	Pavement				
a)	Road Junction condition			√s/U	
b)	Condition of Surfacing			√S/U	
c)	Riding Quality			<i>√</i> 5/U	
d)	Road Camber			√S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of	Yes/No			
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U				
b)	Condition of Abutment & Wing walls, Slab in RCC culverts - S/SRI/U			-S/SRI/U M	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U M	
3	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained  Yes/No				
4.	Compliance History				
a)	Status of ATR	s & any others	,		

**Overall Rating** 

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Mayank fara 22:12:22:20 (Signature)

NAME: MAYANE RAM

DESIGNATION:  $\mathcal{I}\mathcal{E}$