FIELD INSPECTION REPORT

| Date of Inspection: 2 | 2-12-2020 | District: SUPAUL | | |
|---|--|----------------------------|--|--|
| Division: KISHAMIVR | | Length (km): 1.20 km | | |
| Name of the Road: ANDAULI PANDIT TOLA TO LO25 | | | | |
| Scheme/Programme: MAINTENANCE | | | | |
| Package No.: | | Road Id No.: 2100 4 901818 | | |
| Status of the Project: | Ongoing/Completed/Under Maintenance | | | |
| Work is a case of: | New Connectivity/Up gradation/ Maintenance | | | |

| SI. No. | Parameters to be checked | Remarks |
|---------|--|------------|
| 1 | Pavement | State Land |
| a) | Road Junction condition | S/U |
| b) | Condition of Surfacing | √\$/U |
| c) | Riding Quality | √S/U |
| d) | Road Camber | √\$/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | Yes/No |
| f) | Contraction Joints provided or not (CC Pavement) | Yes/No |
| g) | Compaction of flank/slope & raincuts if any | Yes/No |
| 2. | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SŘĽ/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | S/SRI/U M |
| c) | Condition of railings/slab/approach for Bridges | S/SRI/U M |
| 3. | Road Furniture | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No |
| 42 | Compliance History | |
| a) | Status of ATR's & any others | |

Overall Rating :

| Satisfactory (S) | |
|---|-----|
| Satisfactory but requires Improvement (SRI) | SRI |
| Unsatisfactory (U) | |

Mayank Ran 22.12.2200 (Signature)

NAME: MAYAME RAMA

DESIGNATION: $\mathcal{J}.\dot{\mathcal{E}}$

Scanned with CamScanner