

4515 MNP  
**FIELD INSPECTION REPORT**


Date of Inspection : 03-01-21		District: Rohat
Division : R-2(U) division, Saharanpur-1		Length (km): 0.950
Name of the Road: Jalaipur Rajmabura road to Gogahara.		
Scheme/Programme: MAINTENANCE		
Package No.: 4515 MNP.		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
<b>1.</b>	<b>Pavement</b>	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
<b>2.</b>	<b>Gross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
<b>3.</b>	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
<b>4.</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	" S "
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

  
 03-01-21  
 (Signature)

NAME: Mahesh Prasad Saha

DESIGNATION: J.E.