FIELD INSPECTION REPORT

Date of Inspection : District : Bhagalpur			
Division: Bhagalpur Length (Km): 0-7901cm			
	the Road: R. W. D. Block good (Sex Marayan of Tanhi Tola	of (wants	Main
Scheme /	Programme:		
Package No.: 1 Road Id No.: 20703201338			
Status of the Project Ongoing / Completed / Under Maintenance			
Work is a	case of New Connectivity / Up gradation / Maintenance		
SL. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	~8/U	
b)	Condition of Surfacing	SIU	
c)	Riding Quality	S/U	
d)	Road Camber	SIU	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	,
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	!
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U	N.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	5
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	11.0	
Overall Rating			
	Satisfactory (S)		
	Satisfactory but requires Improvement (SRI)		
	Unsatisfactory (U)	S-R.	
Note:			

NAME:

DESIGNATION:

Malmore Signature

Scanned with CamScanner