FIELD INSPECTION REPORT

Date of Inspection: 03/01/2021			District : Katihar	
Division : Katihar			Length (Km): 1.20 KM	
Name of	the Road:	har block Border to Ha	Inlya biyara bura	P40101
Scheme/Programme: Maintenance				
Package No.:		Road	Road ID No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is	/ork is a case of : New Connectivity/Up gradation/Maintenance		are an area of the second	
Sl. No Parameters to be Checked			Remarks	
1).	Pavement 8/U			
a)	Road Junction condition		-S/U	
b)	Condition of Surfacing			
c)	Riding Quality			<i>-</i> 8/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			_Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No	
g)	Compaction of Flank/Slope & Raincuts if any		Yes/No	
2).	Cross Drainage			
a)	Condition of Head walls in Hume Pipe Culverts including its painting		S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.		S/SRI/U N.A	
c)	Condition of Railings/Slab/Approach for Bridges		S/SRI/U N·A	
3).	Dood Furniture			
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained			Yes/No
4).	Compliance History			- In
a)	Status of ATR's & any others			Len
011	Rating	Satisfactory (S)		
Overall	Kating .	Satisfactory but requires Improv	ement (SRI)	5. R.1

Name: Dilip Kumar

Unsatisfactory (U)

Degisnation: J.E

RWD, Works Division, Katihar.

(Signature)