FIELD INSPECTION REPORT

Date of Inspection: 22.12.2.20			District: SUPAUL	
Division: KI SHANDUR			Length (km): 1.80 km	
Name of	the Road: /	VANTOL 70	pwd	
Scheme/	Programme:	MAINTENANCE		
Package	No.:		Road Id No.: 21004-90	1828
			d/Under Maintenance	
			/Up gradation/ Maintenance	
SL No.		Parameters to	be checked	Remarks
Tari	Pavement			
a)	Road Junction condition S/U			√S/U
b)	Condition of Surfacing			√s/u
c)	Riding Quality			√s/U
d)	Road Camber			√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
f)	Contraction Joints provided or not (CC Pavement) Yes/No			
g)	Compaction of flank/slope & raincuts if any			Yes/No
2	Cross Draina	ge .		
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			-S/SRI/U N
3	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No			Yes/No
44.8	Compliance I	listory	The state of the s	可提供的可
a)	Status of ATR	's & any others		Active and the party

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Mayank Lana 22.12.2020 (Signature)

NAME: MAYAME FAMA

DESIGNATION: 22.12.020