

FIELD INSPECTION REPORT

Date of Inspection : 04.01.2021		District : Katihar
Division : Katihar		Length (Km) : 1.075 Km.
Name of the Road : Khaira egadam to mahadali tola		
Scheme/Programme :	Maintenance MMHSY (SC)	
Package No. :	Road ID No. :	
Status of the Project :	Ongoing/Completed/Under Maintenance	
Work is a case of :	New Connectivity/Up gradation/Maintenance	
Sl. No	Parameters to be Checked	Remarks
1).	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	S/U Partially Patched found
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of Flank/Slope & Raincuts if any	✓ Yes/No
2).	Cross Drainage	
a)	Condition of Head walls in Hume Pipe Culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U N/A
c)	Condition of Railings/Slab/Approach for Bridges	S/SRI/U N/A
3).	Road Furniture	
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained	✓ Yes/No
4).	Compliance History	
a)	Status of ATR's & any others	Yes

Overall Rating :	Satisfactory (S)	-
	Satisfactory but requires Improvement (SRI)	SRI
	Unsatisfactory (U)	-

Name : Vijay Kumar
 Designation : A.E. Sameli
 RWD, Works Division, Katihar.


 (Signature)