

FIELD INSPECTION REPORT

Date of Inspection : 09-01-2021	District: PURNIA
Division : BHADAM	Length (km): 1.00 K.M
Name of the Road: KASARA SE L097	
Scheme/Programme: MAINTENANCE	
Package No.: G.T.S.N.Y	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/Y
b)	Condition of Surfacing	S/Y
c)	Riding Quality	S/U
d)	Road Camber	S/Y
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/S/Y/R
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Y/S/No
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

Prumay
09-01-2021
(Signature)

NAME:- PRANOD KUMAR

(J.E)