

FIELD INSPECTION REPORT

Date of Inspection :		District:	
Division :		Length (km):	
Name of the Road: <u>To 5 Garkha thana to maiki-Kariga Aala</u>			
Scheme/Programme:		MAINTENANCE <u>G.T.S.N.V</u>	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		-S/U
b)	Condition of Surfacing		-S/U
c)	Riding Quality		-S/U
d)	Road Camber		-S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		-Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		-Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	SRI ✓
Unsatisfactory (U)	-

NAME:

DESIGNATION:

(Signature)