

FIELD INSPECTION REPORT

Date of Inspection :	03-01-2021	District:	Kahluwan
Division :	Bussol	Length (km):	0.750 km
Name of the Road:	Bhogen Masid Tola to Summa Tola		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance (MMAS) in progress		

Sl No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U - NA
b)	Condition of Surfacing	S/U - NA
c)	Riding Quality	S/U - NA
d)	Road Camber	S/U - NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No - NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No - NA
g)	Compaction of flank/slope & raincuts if any	Yes/No - NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U - NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U - NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U - NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No - Work in progress
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	NA (Work in progress)
Unsatisfactory (U)	—

(Signature) 03/01/2021

NAME: GURJANAND SINGH

DESIGNATION: ASSISTANT ENGINEER