

FIELD INSPECTION REPORT

Date of Inspection : 29.12.2020		District : Munges
Division : Munges		Length (km): 0.300
Name of the Road : L021 to Mudla Tola		
Scheme/Programme : MAINTENANCE		NABARD
Package No.:		Road Id No.: 307
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of :	New Connectivity/Up gradation/Maintenance	
Sl.No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	✓ S / U
b)	Condition of Surfacing	✓ S / U
c)	Riding Quality	✓ S / U
d)	Road Camber	✓ S / U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes / No
f)	Contraction Joints provided or not(CC Pavement)	✓ Yes / No
g)	Compaction of flank/slope & raincuts if any	Yes / No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S / SRI / U
b)	Condition of Abutment & Wing walls Slab in Rcc culverts	✓ S / SRI / U
c)	Condition of railings/slab/approach for Bridges	✓ S / SRI / U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes / No
4	Compliance Histroy	
a)	Status of ATR's & any others - वाह प्रभावित पथ	


Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Mahesh Pd. Singh
A.E.

NAME :

DESIGNATION :


 29.12.2020 (Signature)
 A.E.