FIELD INSPECTION REPORT

Date of Inspection: 04/01/2021 District: Kishan gant			
Division: Kichangant - 1 Length(km): 0.650			
Name of the Road: Gadgaon Road to PMGSY ROAD			
Scheme/Programme: GTSNY			
Package No.: Road Id No.:			
Status of the Project:		Ongoing/Completed /Under Maintenance	
Work is a case of:		New Connectivity/ Up gradation / Maintenance	Remarks
S1. No	Parameters to be checked,		S/U
1.	Pavement		S/U
a)	Road Junction Condition		
b)	Condition of Surfacing		S/U
(c)	Riding Quality		S/U S/U
d)	Road Camber		Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates		
in case of CC Pavement.			Yes/No
f)	Contraction Joints Provided or not (CC Pavement)		
g)	Compaction of flank / shop & raincuts if any		
2.	Cross Prainage		
a)	Condition of head Walls in Hume pipe curverts meraung to		
b)	Condition of Abutment & Wing walls, slab in RCG culverts		- S/SRI/U
c)	Condition of railings/Slab/approach for Bridges		
3.	Road Furniture Road Furniture Yes/No		
a)	Whether sign boards/informatory/cautionary Board/km & 200m		103/10
stones/Pavement road markings are provided and mainta			
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating:

Satisfactory(S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory(U)

(Signature)

AE

NAME: Ranjeet Kumar