

FIELD INSPECTION REPORT

Date of Inspection: 29.12.2020 District: Buxar
 Division: R.D. D. Jharkhand Length (km): 1.03 km
 Name of the Road: NITAN - Aronpur to Ramnagar hse via Salsala water 29 action Tola
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Improvement/Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓
b)	Condition of Surfacing	✓
c)	Riding Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & rainouts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ SSSR
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ SSSR
c)	Condition of railings/slab approach for Bridges	✓ SSSR
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

AM Ward.
29/12/2020
TE

(Signature)