


FIELD INSPECTION REPORT

Date of Inspection :	30/12/2020	District:	Siwan
Division :	Siwan - 2	Length (km):	2-2K.17
Name of the Road:	Ashawnkan Pakar MMHSY path to ZIRadi PMHSY		
Scheme/Programme:	MAINTENANCE	MMHSY	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		✓S/U
b)	Condition of Surfacing		✓S/U
c)	Riding Quality		✓S/U
d)	Road Camber		✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A	Yes/No
g)	Compaction of flank/slope & raincuts if any	OK	Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A	S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m	✓Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		NO

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


(Signature)

NAME: