

FIELD INSPECTION REPORT

Date of Inspection : 31/12/2020		District: SIWAN
Division : SIWAN-2		Length (km): 0.900
Name of the Road: मृत्युञ्जय मिथाँ के दूकान के पास से न्यू मार्केट तक		
Scheme/Programme: MAINTENANCE		MMWJY
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	'NO' Yes/No
f)	Contraction Joints provided or not (CC Pavement)	'Yes' Yes/No
g)	Compaction of flank/slope & raincuts if any	OK Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N/A S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	"NO"

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

31/12/2020

(Signature)

NAME: