FIELD INSPECTION REPORT

Date of Inspection : 0	1 1	EPORT	
Division: School	4.1.2021.	District: Solomash	
Name of the Road: House of Haribar & Scheme/Programme: MAINTENANCE		Length (km): 0.10 KM	
Scheme/Programme:	MADETENAS S	ah to Rojech Paswan home.	
Package No.:	MAINTENANC		
Status of the Project:	TO :-	Road Id No.:	
Want :	Ongoing/Comple	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity	711	

SI. No.	Parameters to be checked		
1.	Pavement	Remarks	
a)	Road Junction condition	√8/U	
b)	Condition of Surfacing	√S/U	
c)	Riding Quality	√8/U	
d)	Road Camber	√8/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	₩es/No	
g)	Compaction of flank/slope & raincuts if any	Wes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	≥8/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	· S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	¥∕cs/No	
4.	Compliance History		
a)	Status of ATR's & any others	N 0.	

Overall Rating

Satisfactory (S)	0	
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

NAME: My LING