

FIELD INSPECTION REPORT

Date of Inspection : 29-12-2020 District: PURNIA
 Division : DHAMDARA Length (km): 2.350 K.M
 Name of the Road: DAKAITA Dih Tola To DAKAITA Main Road
 Scheme/Programme: MAINTENANCE
 Package No.: MMUSY (CT) Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/S
b)	Condition of Surfacing	S/S
c)	Riding Quality	S/S
d)	Road Camber	S/S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & ravelments if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/S/SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/S/SRI
c)	Condition of railings/slab/approach for Bridges	S/S/SRI
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)
 Satisfactory but requires Improvement (SRI)
 Unsatisfactory (U)

S

NAME: PRAMOD KUMAR
 (J.E)

Purnia
 29-12-2020
 (Signature)