

FIELD INSPECTION REPORT

Date of Inspection: 31.12.2020 District: PUNJAB
 Division: Dhamdaha Length (km): 0.640 KM
 Name of the Road: To 1 se Samwari Ashan
 Scheme Programme: MAINTENANCE
 Package No: MMB 03 Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Upgradation/Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓
b)	Condition of Surfacing	✓
c)	Binding Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/S/PU
b)	Condition of Abutment & Wing walls. Slab in RCC culverts	S/S/PU
c)	Condition of railings/slab/approach for Bridges	S/S/PU
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stores/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Prumod
 31.12.2020
 (Signature)

NAME: PRUMOD KUMAR
 (20)