

FIELD INSPECTION REPORT

Date of Inspection :	24/12/2020	District:	Bhojpur
Division :	Ara	Length (km):	0.6
Name of the Road:	Puliya Ke Paa Se Dholm		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	Yes	
b)	Condition of Surfacing	Yes	
c)	Riding Quality	Yes	
d)	Road Camber	Yes	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S.S.P.I	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S.S.P.I	
c)	Condition of railings/slab/approach for Bridges	S.S.P.I	
3.	Road Furniture		
a)	Whether sign boards/informatry/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	Yes/No	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

NAME:

Sunil Kumar Prasad.

(Signature)

24/12/2020

2020/12/29 16:07