## FIELD INSPECTION REPORT

Date of Inspection: 0 3-01-20			District: Roktos	
Division: RwD(w) Livisin, Sasaran1			Length (km):	4355 KM
Name of	the Road:	051 70	Balizambri	
Scheme	Programme:	MAINTENANCE		
Package	No.:	212654	Road Id No.:	
Status of the Project:			d/Under Maintenance	
Work is a case of:		New Connectivity/	Up gradation/ Maintenance	
SI. No.		Parameters to	be checked	Remarks
1.	Pavement			

SI. No.	Parameters to be checked	Remarks		
1.	Pavement			
a)	Road Junction condition	✓ S/U		
b)	Condition of Surfacing	S/U		
c)	Riding Quality	_ S/U		
d)	Road Camber -	- S/U		
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	_Yes/No		
f)	Contraction Joints provided or not (CC Pavement)	Yes/No.		
g)	Compaction of flank/slope & raincuts if any	Yes/No		
2	Gross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting.	S/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U		
c)	Condition of railings/slab/approach for Bridges	S/SRI/U		
3.	Road Purniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No		
4	Compilaries Pringolov.	7		
8)	Status of ATR's & any others	43		

Overall Rating

Satisfactory (S)	33 "
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Moscopolsof 03-01-81.

(Signature)

NAME: Makesh Pordad Sah

DESIGNATION: JR